



Safety Gate: Rapid Alert System for dangerous non-food products

Alert number	A12/0773/15
Category	Motor vehicles
Type of alert	Products with serious risks
Product user	Consumer
Product	Motorcycles
Brand	Triumph
Name	Speed Triple 1050i R, Speed Triple 1050i R 94, Daytona 675 R
Type / number of model	Type: H67, 515NV; EC type-approval: e11*2002/24*1592*, e11*2002/24*1049*
Batch number / Barcode	Vehicles manufactured between 2014 and 2015 are affected.
OECD Portal Category	77000000 - Automotive
Description	Motorcycle
Country of origin	United Kingdom
Alert submitted by	Germany
Risk type	Injuries
Risk	Due to insufficient tightening, the connecting rod nut for the shock absorber may become detached and thus impair the shock-absorbing effect. In the worst-case scenario the rider may lose control over the motorcycle.
Measures adopted by notifying country	Recall of the product from end users
Products were found and measures were taken also in	The Netherlands, Ireland, France, Malta, Denmark, United Kingdom, Greece, Sweden, Hungary
Images	No pictures are available