



Safety Gate: Rapid Alert System for dangerous non-food products

| | |
|---|--|
| Alert number | A12/00014/21 |
| Category | Motor vehicles |
| Type of alert | Products with serious risks |
| Product user | Consumer |
| Product | Motorcycle |
| Brand | Honda |
| Name | CRF1000/1100A/D |
| Type / number of model | e4*168/2013*00033*02, e4*168/2013*00115*00 |
| Company recall code | 3LK |
| Production dates | The affected vehicles were manufactured between 29 November 2017 and 19 October 2020. |
| OECD Portal Category | 77000000 - Automotive |
| Description | Model: CRF1000A2, CRF1000D2, CRF1100A2, CREF1100A4, CRF1100D2, CRF1100D4; Model years: 2018 - 2021. |
| Country of origin | Japan |
| Alert submitted by | Portugal |
| Counterfeit * | NO |
| Risk type | Injuries |
| Technical defect | The fuel filter may be clogged by zinc oxide particles, generated during the welding process of the fuel tank. This could cause the motorcycle to lose power or the engine to stall, increasing the risk of an accident. / |
| Risk | |
| Measures adopted by notifying country | Recall of the product from end users |
| Products were found and measures were taken also in | Poland |
| Images | No pictures are available |